

# Statistical Process Control

MSc: Statistics and Actuarial-Financial Mathematics

Konstantinos Bourazas  
kbourazas@aegean.gr

Department of Statistics and Actuarial-Financial Mathematics

Course 2

February 26, 2026

## $\bar{X}$ and $R$ charts

- Many quality characteristics are **measured on a numerical scale**: length, weight, strength, concentration, temperature, ...
- We typically do not inspect items one by one
  - ▶ Instead, we collect small **rational subgroups** of size  $m$  at regular time points
  - ▶ Within each subgroup we summarise the data by a few statistics that we monitor over time
- The  $\bar{X}$  **chart** monitors the process **mean level**
- The  $R$  **chart** monitors the process **short-term variability**
- In practice both charts are used **together** as a stable mean is meaningless without stable variability, and vice versa

## Data collected in rational subgroups

- At time point  $i$  we observe  $m$  items


$$X_{i1}, X_{i2}, \dots, X_{im}, \quad i = 1, 2, \dots, n$$

- **Rational subgrouping**: items within a subgroup should be produced under **nearly the same conditions**, so that between-subgroup differences can reveal process changes
- In practice  $m$  is typically **4 or 5**
  - ▶ The subgroup mean  $\bar{X}_i$  is approximately normal by the **Central Limit Theorem**, even when individual items are not
  - ▶ Larger  $m$  is rarely needed for this purpose
- Phase I uses  $n$  subgroups collected when the process is believed to be **In Control (IC)**. Then, Phase II follows and it monitors future subgroups using the limits established in Phase I


## Central Limit Theorem and subgroup means

Even if individual observations  $X_{ij}$  are skewed, the subgroup mean  $\bar{X}_i$  becomes much closer to normal for  $m = 5$

Skewed raw observations



Means of subgroups of size 5



## Subgroup summaries $\bar{X}_i$ and $R_i$

- For each subgroup  $i$  we compute two basic summaries

$$\bar{X}_i = \frac{1}{m} \sum_{j=1}^m X_{ij}, \quad R_i = \max_{1 \leq j \leq m} X_{ij} - \min_{1 \leq j \leq m} X_{ij}$$

- Across all  $n$  Phase I subgroups we also compute the overall averages

$$\bar{\bar{X}} = \frac{1}{n} \sum_{i=1}^n \bar{X}_i, \quad \bar{R} = \frac{1}{n} \sum_{i=1}^n R_i$$

- Interpretation

- ▶  $\bar{X}_i$  tracks the **current process level** at time  $i$
- ▶  $R_i$  tracks the **short-term spread** within the subgroup at time  $i$

## If the IC parameters were known

- Assume for a moment that both  $\mu_0$  and  $\sigma$  are **known**
- To check whether the process mean is IC at time  $i$ , we can test

$$H_0: \mu = \mu_0 \quad \text{vs} \quad H_1: \mu \neq \mu_0$$

- A natural test statistic is

$$Z_i = \frac{\bar{X}_i - \mu_0}{\sigma/\sqrt{m}} \stackrel{H_0}{\sim} N(0, 1)$$

- We declare OOC at time  $i$  when  $|Z_i| > Z_{1-\alpha/2}$ , which is equivalent to

$$\bar{X}_i > \mu_0 + Z_{1-\alpha/2} \frac{\sigma}{\sqrt{m}} \quad \text{or} \quad \bar{X}_i < \mu_0 - Z_{1-\alpha/2} \frac{\sigma}{\sqrt{m}}$$

- In practice  $\mu_0$  and  $\sigma$  are unknown and must be estimated from Phase I data
- This is why  $\bar{\bar{X}}$ ,  $\bar{R}$ , and the constants  $d_1(m)$  and  $d_2(m)$  appear in the final control limits

# Why estimate $\sigma$ with the range instead of the sample SD

- A natural estimator of  $\sigma$  is the pooled sample standard deviation  $\bar{s}$
- So why do  $\bar{X}$  and  $R$  charts use  $\bar{R}$  instead
- **Historical reason**
  - ▶ When Shewhart charts were introduced, computing a square root for every subgroup by hand was time consuming
  - ▶ The range requires only a **simple subtraction**, so it was much easier to compute routinely
- **Statistical reason**
  - ▶ For small subgroup sizes, especially  $m = 4$  **or**  $5$ , the range retains nearly all the information about  $\sigma$  that the sample SD contains
  - ▶ The relative efficiency of  $\bar{R}$  compared with  $\bar{s}$  is **above** 85% for  $m \leq 6$
  - ▶ For larger  $m$  the efficiency drops, and  $\bar{X}$  **and**  $s$  **charts** are preferred
- Today the computational advantage is less important, but  $\bar{X}$  **and**  $R$  **charts** remain a common industry default for  $m \leq 6$

## Estimating $\sigma$ from the average range

- In an  $\bar{X}$  **and**  $R$  **chart** we need an estimate of the process standard deviation  $\sigma$ 
  - ▶ The  $\bar{X}$  chart limits depend on  $\sigma/\sqrt{m}$ , the standard error of the subgroup mean
  - ▶ The  $R$  chart limits depend on how much the range  $R_i$  varies when the process is **IC**
- Instead of estimating  $\sigma$  from subgroup standard deviations, Shewhart charts estimate it from the **average range**  $\bar{R}$
- To turn  $\bar{R}$  into an estimate of  $\sigma$ , we need to know what the range looks like under **IC** normal sampling
- Specifically, we need the **mean** and **standard deviation** of the standardised range  $R_i/\sigma$  — and these depend only on  $m$

## The constants $d_1(m)$ and $d_2(m)$

- When the process is **IC** and normal,  $X_{ij} \sim N(\mu_0, \sigma^2)$ , the standardised range  $R_i/\sigma$  has a distribution that depends **only on  $m$**
- We define two constants that capture this distribution

$$d_1(m) = E\left[\frac{R_i}{\sigma}\right], \quad d_2(m) = \sqrt{\text{Var}\left[\frac{R_i}{\sigma}\right]}$$

- Because they depend only on  $m$ , they can be computed once and tabulated (see next slide)
- They give us plug-in estimators based on  $\bar{R}$

$$\hat{\sigma} = \frac{\bar{R}}{d_1(m)}, \quad \widehat{\text{SD}}(R_i) = \frac{d_2(m)}{d_1(m)} \bar{R}$$

- $\hat{\sigma}$  feeds into the  $\bar{X}$  chart limits;  $\widehat{\text{SD}}(R_i)$  feeds into the  $R$  chart limits

## Table of constants $d_1(m)$ and $d_2(m)$ (Qiu, Table 3.1)

$m$	$d_1(m)$	$d_2(m)$	$m$	$d_1(m)$	$d_2(m)$
2	1.128	0.853	14	3.407	0.763
3	1.693	0.888	15	3.472	0.756
4	2.059	0.880	16	3.532	0.750
5	2.326	0.864	17	3.588	0.744
6	2.534	0.848	18	3.640	0.739
7	2.704	0.833	19	3.689	0.734
8	2.847	0.820	20	3.735	0.729
9	2.970	0.808	21	3.778	0.724
10	3.078	0.797	22	3.819	0.720
11	3.173	0.787	23	3.858	0.716
12	3.258	0.778	24	3.895	0.712
13	3.336	0.770	25	3.931	0.708

## Control limits for the $\bar{X}$ chart

- From the previous slide, we declare OOC when  $\bar{X}_i$  falls outside  $\mu_0 \pm Z_{1-\alpha/2} \sigma / \sqrt{m}$
- In practice both  $\mu_0$  and  $\sigma$  are unknown, so we replace them with their Phase I estimates

$$\mu_0 \rightarrow \bar{\bar{X}}, \quad \frac{\sigma}{\sqrt{m}} \rightarrow \frac{\bar{R}}{d_1(m)\sqrt{m}} = \hat{\sigma}_{\bar{X}}$$

- The Upper Control Limit (UCL), the Centre Line (CL), and the Lower Control Limit (LCL) are:

$$\text{UCL} = \bar{\bar{X}} + \frac{Z_{1-\alpha/2}}{d_1(m)\sqrt{m}} \bar{R}, \quad \text{CL} = \bar{\bar{X}}, \quad \text{LCL} = \bar{\bar{X}} - \frac{Z_{1-\alpha/2}}{d_1(m)\sqrt{m}} \bar{R}$$

- The structure is simply  $\bar{\bar{X}} \pm Z_{1-\alpha/2} \hat{\sigma}_{\bar{X}}$ , identical to the known-parameter case with both parameters estimated
- In practice  $Z_{1-\alpha/2} = 3$  is the universal convention
  - ▶ It corresponds to  $\alpha = 2 \Phi(-3) \approx 0.0027$ , i.e. a **false alarm rate of 0.27% per subgroup** when IC
  - ▶ Equivalently, under IC the chart signals on average once every  $1/0.0027 \approx 370$  subgroups, a concept we return to shortly
- A point outside the limits is evidence that the process mean is **OOC**

## Control limits for the $R$ chart

- We monitor  $R_i$  around its IC baseline  $\bar{R}$
- The estimated standard deviation of  $R_i$  is  $\widehat{SD}(R_i) = d_2(m) \bar{R} / d_1(m)$
- The  $R$  chart limits are therefore

$$\text{UCL} = \left(1 + \frac{Z_{1-\alpha/2} d_2(m)}{d_1(m)}\right) \bar{R}, \quad \text{CL} = \bar{R}, \quad \text{LCL} = \left(1 - \frac{Z_{1-\alpha/2} d_2(m)}{d_1(m)}\right) \bar{R}$$

- Since  $R_i \geq 0$ , a negative LCL is set to 0
  - ▶ For  $m = 5$ :  $\text{LCL} = (1 - 3 \times 0.864/2.326) \bar{R} = -0.114 \bar{R} < 0$ , so  $\text{LCL} = 0$
  - ▶ The LCL becomes positive only for  $m \geq 7$
- A point above the UCL signals **increased variability**; a point below a positive LCL signals **decreased variability** (often a sign of quality improvement)

## Phase I workflow for $\bar{X}$ and $R$ charts

- Collect  $n$  rational subgroups of size  $m$  under conditions believed to be **IC**
- Compute the subgroup summaries  $\bar{X}_i$  and  $R_i$  for each  $i = 1, \dots, n$
- Compute  $\bar{\bar{X}}$  and  $\bar{\bar{R}}$  and obtain  $d_1(m)$  and  $d_2(m)$  from a table
- Choose  $Z_{1-\alpha/2}$  for the desired false alarm rate
  - ▶ A common default is  $Z_{1-\alpha/2} = 3$ , which makes false alarms rare under IC
  - ▶ The exact choice depends on the cost of false alarms versus missed detection
- **First** plot the  $R$  chart and check that variability is stable
  - ▶ The  $\bar{X}$  chart limits depend on  $\bar{\bar{R}}$ , so if variability is unstable those limits are not trustworthy
  - ▶ Only if the  $R$  chart looks stable do we proceed to the  $\bar{X}$  chart
- If special causes are found, investigate, adjust, and rebuild the Phase I baseline


## Phase II interpretation using the established limits

- In Phase II, new subgroups arrive sequentially and we compute  $\bar{X}_i$  and  $R_i$  each time
- We compare each new point against the Phase I control limits
  - ▶ If a point crosses a limit, we treat it as an **alarm** and investigate the process
  - ▶ If points remain within limits, the data are consistent with the IC baseline
- When an alarm occurs, the practical response is also sequential
  - ▶ Stop and diagnose when appropriate
  - ▶ Remove the special cause and adjust the process
  - ▶ Restart monitoring after we are confident the process is back to IC

## Example 3.1 Injection molding process

- We monitor an injection molding process where the quality characteristic is the **compressive strength** of manufactured parts
- $n = 20$  Phase I subgroups are collected, each with subgroup size  $m = 5$
- For each subgroup, we compute  $\bar{X}_i$  and  $R_i$
- We then build Phase I limits using  $Z_{1-\alpha/2} = 3$  and the constants for  $m = 5$
- Finally, we monitor four additional Phase II subgroups and check whether the charts signal

## Example 3.1 $\bar{X}$ and $R$ charts



## Chart performance: the Average Run Length

- How do we measure how well a control chart behaves when the process is **IC**?
- At each time point, the probability of a false alarm is  $\alpha$  independently of all other time points, so the number of subgroups until the first false alarm follows a **Geometric**( $\alpha$ ) distribution
- Its mean is the **IC Average Run Length**

$$ARL_0 = \frac{1}{\alpha}$$

- For the conventional choice  $Z_{1-\alpha/2} = 3$ , i.e.  $\alpha = 0.0027$

$$ARL_0 = \frac{1}{0.0027} \approx 370$$

- Interpretation: when the process is IC, the chart signals on average once every **370 subgroups**
- A larger  $ARL_0$  means fewer false alarms. In practice, we want  $ARL_0$  to be large under IC and small when the process shifts

## Multiple testing in Phase I: the overall false alarm rate

- In Phase I we apply the chart to  $n$  subgroups **simultaneously**
- Even if the process is IC throughout, each subgroup has probability  $\alpha$  of triggering a false alarm independently, so

$$\begin{aligned}P(\text{at least one false alarm}) &= 1 - P(\text{no false alarm in any of the } n \text{ subgroups}) \\ &= 1 - (1 - \alpha)^n = \tilde{\alpha}\end{aligned}$$

- This is directly analogous to the **Family-Wise Error Rate (FWER)** in multiple testing
- For  $\alpha = 0.0027$  and typical Phase I sample sizes

$$n = 10 \Rightarrow \tilde{\alpha} \approx 2.7\%, \quad n = 20 \Rightarrow \tilde{\alpha} \approx 5.2\%, \quad n = 50 \Rightarrow \tilde{\alpha} \approx 12.6\%$$


- Consequence: even with the conservative  $3\sigma$  limits, spurious signals in Phase I are not negligible for large  $n$
- If tighter control of  $\tilde{\alpha}$  is needed, choose  $\alpha$  via  $\alpha = 1 - (1 - \tilde{\alpha})^{1/n}$

## Beyond the $3\sigma$ rule: run patterns


- A control chart can reveal problems even when **no point crosses a limit**
- Non-random patterns such as long runs, trends, or periodic behaviour are unlikely under IC and suggest special causes
- The **Western Electric Handbook (1956)** codified four supplementary rules; the process is declared OOC if any of the following occur
  - ▶ One point outside the  $3\sigma$  limits
  - ▶ Two out of three consecutive points beyond the  $2\sigma$  limits
  - ▶ Four out of five consecutive points more than  $1\sigma$  from the centre line
  - ▶ Eight consecutive points on the same side of the centre line
- The motivation is clear: these patterns are unlikely under IC and may indicate a small or gradual shift that a single point cannot detect

# Western Electric rules in four examples


**Rule 1 One point beyond  $3\sigma$**




**Rule 2 Two of three beyond  $2\sigma$**



**Rule 3 Four of five beyond  $1\sigma$**



**Rule 4 Eight in a row on one side**



## Limitations of the Western Electric rules

- The rules are largely **ad hoc**, as they were motivated by intuition rather than derived from a formal statistical framework
- Applying multiple rules simultaneously **inflates the Type I error rate**
  - ▶ Each additional rule increases the chance of a false alarm
  - ▶ The rules are correlated, so the overall  $\tilde{\alpha}$  is difficult to compute or control
- We discuss them here for **didactic purposes**, as they build intuition about what non-random behaviour looks like on a control chart
- In modern practice, **CUSUM and EWMA charts** offer a principled and statistically rigorous solution to detecting small or gradual shifts, with explicit control of the false alarm rate